JTL FIRMWARE VARIATIONS		SDPA
VERSION	**DESCRIPTION**	**DATE**
v0.00.0	Original issue.	July 2005
v0.00.1	Time starts at 1/1/2004. Defrost co-ordinator operation corrected. Time since start of last defrost added on item 224 to allow time delay at start of co-ordinated defrost to be reduced. "Exclude from optimization" error corrected.	June 2007
V0.00.2	Time since start of last defrost. Calculation of time since start of last defrost corrected. Lockup condition which can theoretically occur if network defrost initiation during defrost recovery removed. Forced defrost requirement no (DRN) now cleared on defrost to be consistent with normal DRN operator. Site absolute humidity display added on item 246. No of defrosts a day allow up to 12. Circuit no error on comms corrected. Cabinet temperature calculation changed when both air off and evaporators sensors faulty. Display shows air on temperature in this condition. Error in Multicast handling corrected. Site absolute humidity added on item 246.	Nov 2007
v0.00.3	Service log error introduced in v0.00.2 corrected.	Mar 2008
v0.00.4	Control temperature can be selected as air off or cabinet on item 275. No cooling mode added. Time delay added for all sensors faulty alarm. Broadcast timers and Multicast data supported. Lighting control will operate by Multicast operation when available on site. Errors in site temperature and humidity broadcast receive corrected.	May 2009