| JTL FIRMWARE VARIATIONS | | LAPE |
|---|---|---|
| **VERSION** | **DESCRIPTION** | **DATE** |
| v0.00.0 | Production issue. | Feb 2004 |
| v0.00.1 | Air off alarm averaging on item 27 made operational for display purposes.<br>Operation of defrost recovery corrected.<br>Broadcasting allowed when MU in use.<br>Item 422 shows air off sensor data not processed data.<br>Display switch data on network report pages corrected. | Nov 2004 |
| v0.00.2 | Absolute humidity broadcast data added on item 246.<br>Site temperature and relative humidity broadcast data operation amended.<br>Trim heater control added.<br>Start of time now 1st Jan 2004. | Jan 2006 |
| v0.00.3 | Time since start of defrost added in item 224.<br>Defrost coordinator present timer operation corrected.<br>Exclude from optimisation error corrected.<br>No of defrosts a day now 12 maximum.<br>Theoretical potential lockup prevented when network defrost command occurs during.<br>defrost recovery.<br>Forced defrost requirement now handled as standard defrost requirement.<br>Cabinet temperature calculations changed in the situation where both air off and evaporators sensors are faulty. Air on temperature used in this condition.<br>Error in Multicast handling corrected. | Nov 2007 |