


NJ21

For Termination of Jnet network using "blue cores"
at network controller type NC331 and NC335



NOTE:

Connections made to screw terminals connections should be made using unscreened 2 core cable. (eg 7/0.2-2)

If screened cable is used, the screen should ONLY be connected to earth at one end or left unconnected.

(UNDER NO CIRCUMSTANCES SHOULD THE SCREEN BE CONNECTED AT BOTH ENDS)

The flexible cable should be terminated in the correct size of boot-lace ferrule.

THIS IS AN UNCONTROLLED COPY - UNLESS STAMPED WITH CONTROLLED COPY STAMP

ISSUE	DESCRIPTION	APP'D	DATE	 JTL SYSTEMS LTD. 41 KINGFISHER COURT, HAMBRIDGE RD, NEWBURY, BERKSHIRE. RG14 5SJ TEL: 01635-263646 FAX: 01635 263647		
2	CHANGES	SzN	10/16			
1	ORIGINAL ISSUE	MJK	06/15			
TITLE: NJ21 For Termination of Jnet network using "blue cores" at network controller						
DRG TYPE: APPLICATION DRAWING						
PROJ:		DRG No:		SHT	OF	ISS.
		04504		1	1	2