
## **NJ22**

## For Termination of Jnet network using "blue cores" at network controller type NC331 and NC335



## NOTE:

1. Connections made to screw terminals connections should be made using unscreened 2 core cable. (eg 7/0.2-2)

If screened cable is used, the screen should ONLY be connected to earth at one end or left unconnected.

(UNDER NO CIRCUMSTANCES SHOULD THE SCREEN BE CONNECTED AT BOTH ENDS)

The flexible cable should be terminated in the correct size of boot-lace ferrule.

## THIS IS AN UNCONTROLLED COPY - UNLESS STAMPED WITH CONTROLLED COPY STAMP

ISSUE	DESCRIPTION	APP'D	DATE		JTL SYSTEMS LTD.			
				/itl/	41 KINGFISHER COURT, HAMBRIDGE RD, NEWBURY, BERKSHIRE. RG14 5SJ			
1	ORIGINAL ISSUE	SzN	09/16		TEL: 01635-263646 FAX: 01635 263647			
NJ22 For Termination of Jnet network				DRG TYPE: APPLICATION DRAWING				
using "blue cores" at network controller				PROJ:	DRG No: 04718	sнт <b>1</b>	0F <b>1</b>	ISS. <b>1</b>