


## NJ03 CONNECTIONS



### NOTE:

All connections made to screw terminals connections should be made using unscreened 2 core cable. (eg 7/0.2-2)

If screened cable is used, the screen should ONLY be connected to earth at one end or left unconnected.

(UNDER NO CIRCUMSTANCES SHOULD THE SCREEN BE CONNECTED AT BOTH ENDS)

The flexible cable should be terminated in the correct size of boot-lace ferrule.

THIS IS AN UNCONTROLLED COPY - UNLESS STAMPED WITH CONTROLLED COPY STAMP

ISSUE	DESCRIPTION	APP'D	DATE
1	UPDATED	MJK	10/04
1	ORIGINAL ISSUE	MJK	07/04

TITLE:

NJ03 CONNECTIONS



**JTL SYSTEMS LTD.**

41 KINGFISHER COURT, HAMBRIDGE RD,  
NEWBURY, BERKSHIRE. RG14 5SJ  
TEL: 01635-263646 FAX: 01635 263647

PROJ:

DRG No:

03122

SHT

OF

ISS.

1

1

2