

JTL FIRMWARE VARIATIONS		TA231
VERSION	DESCRIPTION	DATE
v0.00.0	Production issue as TA230 with contact inputs removed.	Oct 2008
v0.00.1	Defrost overrun and unit shutdown added to channel alarms	March 2007
v1.00.2	Moved to PC03208 platform	Oct 2007
v1.00.3	Fix spurious awake problem to wrong unit number	Nov 2007
v1.00.4	Set brown out reset fuse in configuration byte	June 2008