

<b>JTL FIRMWARE VARIATIONS</b>		<b>HP230 HP240</b>
<b>VERSION</b>	<b>DESCRIPTION</b>	<b>DATE</b>
v0.00.0	Original issue.	Mar 2011
v0.00.1	Misalignment of pressure transducer faults corrected. Suction pressure transducer faults alarmed. Download parameter operation supported.	Apr 2011
v0.00.2	R408A added to refrigerants. R407A table adjusted slightly for "dew". Download parameter sequence amended in fault conditions.	July 2011
v0.00.3	Separate output (relay 2) added to enable external control of heat exchanger superheat. Maximum and minimum PEV valve opening operation included in algorithms. Maximum slow rate of PEV outputs added on item 47.	Nov 2011