
NJ22 For Termination of Jnet and Ethernet shared in a single CAT5 cable



NOTE:

1. Connections made to screw terminals connections should be made using unscreened 2 core cable. (eg 7/0.2-2)

If screened cable is used, the screen should ONLY be connected to earth at one end or left unconnected.

(UNDER NO CIRCUMSTANCES SHOULD THE SCREEN BE CONNECTED AT BOTH ENDS)

The flexible cable should be terminated in the correct size of boot-lace ferrule.

2. When using ethernet and Jnet on same cable, separated termination is required at Network Controller patch panel.

THIS IS AN UNCONTROLLED COPY - UNLESS STAMPED WITH CONTROLLED COPY STAMP

ISSUE	DESCRIPTION	APP'D	DATE		JTL SYSTEMS LTD.			
				(11: ا	41 KINGFISHER COURT, HA	MBDIDG	E DD	
1	REVIEWED	SzN	09/16	/1Tl/	NEWBURY, BERKSHIRE. RG14 5SJ			
1	ORIGINAL ISSUE	RMSJ	10/15	CJ	TEL: 01635-263646 FAX: 01635 263647			
TITLE	NJ22 For Termination of Jnet and	APPLICATION DRAWING						
shared in a single CAT5 cable			PROJ:	DRG No:	SHT	OF	ISS.	
onarea in a single critic saste					04568	1	1	2