

CPC LEAK DETECTOR INTERFACE FIRMWARE VARIATIONS		RL120
VERSION	DESCRIPTION	DATE
v0.00.0	Original issue.	Aug 2004
v0.00.1	PROM checksum error corrected.	Nov 2004
v0.00.2	Low flow fault alarm can be selectively disabled for each channel.	Apr 2005
v0.00.3	Datalogging dependency error corrected.	Nov 2005